

Year	Model	Style	Part #	Description	Condition	Storage #
Acura						
1991	Integra	4dr sdn	FB4109BTN	Heated back glass	Good	R1S6
BMW						
1997 - 03	5 series	4dr sdn	FB20016GT	Heated back glass	Good	R1S15
Chevrolet						
1993	Camaro	2dr Cpe	DD8264GT	Left front door glass	Good	U1S15
1986	S10	ALL	DD6424GT	Left front door glass	Good	U1S18
1985	Sprint	4dr Hatchback	FB2885GT	Heated back glass	Good	R2S7
1988	Sprint	2dr Htbk	Part #	Right rear quarter glass	Good	U1S12
1990	Sprint	2dr Hatchback	FQ3928GT	Left rear quarter glass	Good	U1S13
1990	Sprint	2dr Hatchback	FQ3927GT	Right rear quarter glass	Good	U1S13
1989	Sprint	4dr Hatchback	FB3937GT	Heated back glass	Good	R2S6
1990	Sprint	4dr Hatchback	FB3937GT	Heated back glass	Good	R2S7
1990	Sprint	4dr Hatchback	FQ3936GT	Left rear quarter glass	Good	U1S13
1990	Sprint	4dr Hatchback	FQ3935GT	Right rear quarter glass	Good	U1S13
2001	Tahoe	4dr Utility	DB9787YPY	Privacy heated back glass	Good	R2S7
Dodge						
2000	Dakota	ALL	DB9591YPY	Heated privacy back glass	Good	R2S12
Ford						
86 - 94	Aerostar	ALL		Privacy heated back glass	Good	R2S3
86 - 94	Aerostar	ALL		Privacy left rear quarter glass	Good	U1S17
1996	Aerostar	ALL	DD8728GT	Right front door glass	Good	U1S16
2001	Escape	4dr Utility	Part #	Right rear quarter glass	Good	U1S17
01 - 11/28/01	Escape	4dr Utility	DB9757YPY	Privacy heated back glass	Good	R2S3
1992	Econoline	Van	DD8016GT	Left door glass	Good	U2
2000	F150	2dr Supercab	DQ8977YP	Right moveable quarter glass	Good	U2
2001	F150	2dr Supercab	DQ9497YP	Left moveable quarter glass	Good	U2
2000	F150	All	DD8975GT & DD8976GT	Left & right door glass	Good	U2
1988	F350	All	DD7210GT & DD7211GT	Left and right door glass	Badly scratched	U2
1967	Mustang	2dr Cpe	Part #	Right front door glass	Good	U1S17
2000-2002	Mustang	All	DD9655GT	Right door glass	Minor scratch	U2
1987	Mustang	2dr Coupe	DQ7206GT	Right quarter glass	Good	U2
1980	Mustang	2dr Htbk	DB5873	Heated Back Glass	Good	R1S5
1990	Taurus	4dr Wagon	DB6984GT	Heated back glass	Good	R2S4
1983	Ranger	2dr std cab W/O vent	DD6412GT	Left door glass	Good	U2
98 - 05	Ranger	ALL	DB9288GTY	OEM back glass	Good	R2S1
1999	Windstar	Mini van	DB9555YP	Privacy heated back glass	Small scratches	R2S4
GMC						
1978	K-series	All	DT1135GT	Back Glass	Minor scratches	R2S5
2005	Sierra pickup	All	DB9483YP	Heated back glass - privacy	Good	R2S6
1996	Sonoma	All	DB8427GT	Back glass	Good	R2S6
1994	Yukon	2dr Utility	DQ8318YP	Right quarter glass - privacy	Good	R2S7
Honda						
1988	Accord	4dr sdn	FB3183GT	Heated back glass	Good	R1S4

1990	Accord	2dr Cpe	FB4222GT	Heated back glass	Good	R1S11
1990	Accord	2dr Cpe	FD4219GT	Left front door glass	Good	U1S18
1980	Civic	2dr htbk	FB2011GT	Heated back glass	Good	R1S7
1985	Civic	2dr htbk	FB2709GT	Heated back glass	Good	R1S5
1990	Civic	4dr Sdn	Part #	Left rear door glass	Good	U1S12
1991	Civic	2dr Cpe	FB3723GT	Heated back glass	Good	R1S11
1991	Civic	2dr Cpe	FD3719GT	Right front door glass	Good	U1S12
1996	Civic	4dr sdn	FB5581GT	Heated back glass	Good	R1S8
2000	Civic	2dr Cpe	Part #	Left front door glass	Good	U1S12
2002	Civic	2dr Cpe	Part #	Left front door glass	Good	U1S16
2002	Civic	2dr Cpe	FQ21176GTY	Left quarter glass	Encapsulated moulding damaged	U1UP
1987	CRX	2dr htbk	FB3184GT	Heated back glass	Good	R1S2
1982	Prelude	2dr cpe	FB2005	Heated backglass	Hole filler	R1S4
1990	Prelude	2dr cpe	FB3619GT	Heated backglass	Good	R1S10
1995	Odyssey	Minivan	Part #	Left rear door	Good - Aftermarket tint	U1S16

Hyundai

1987	Excel	Hatchback	FB3293	Heated Back Glass	Good	R1S12
1989	Excel	Hatchback	FB3293	Heated Back Glass	Good	R1S3
1991	Excel	4dr sdn	FB4070GT	Heated Back Glass	Good	R1S12
1994	Elantra	4DR Sdn	FB4499	Heated Back Glass	Good	R1S12
1991	Sonota	4dr sdn	FB3919	Heated Back Glass	Good	R1S12
2000	Tiburon	2dr cpe	Part #	Left front door glass	Good	U1S18

Infiniti

1992	G20	4dr sdn	FB4387GT	Heated back glass	Good	R1S13
------	-----	---------	----------	-------------------	------	-------

Mazda

1986	323	Htbk	FB3109	Heated Back Glass	Good	R1S9
1989	323	4dr sdn	FB3109	Heated Back Glass	Good	R1S9
1984	626	2dr cpe	FB2535	Heated back Glass	Good	R1S9
1990	626	4dr Sdn	FD3641BT	Right rear door glass	Good	U1S19
1990	626	4dr Sdn	FD3641GT	Right rear door glass	Good	U1S15
1990	626	4dr Sdn	FD3642BT	Left rear door glass	Good	U1S13
1990	626	4dr Sdn	FD3640BT	Left front door glass	Good	U1S15
1990	626	4dr Sdn	FD3639BT	Right front door glass	Good	U1S15
1991	626	4dr sdn	FB3645	Heated back Glass	Good	R1S2
1994	626	4dr Sdn	FD4677GT	Left rear door glass	Good	U1S19
1994	626	4dr Sdn	FB4678GT	Heated back glass	Good	R1S9
1986	B2000	ALL	FB3098GT	Back Glass	Good	R2S13
1989	B2200	ALL	FB3098GT	Back Glass	Good	R2S13
1989	MPV	Minivan	FB3871YP	Heated Back Glass	Good	R1S10
1991	MPV	Minivan	FB3871	Heated Back Glass	Good	R1S8
1994	Protege	4dr sdn	FB4142	Heated Back Glass	Good	R1S8

Mercedes Benz

1995	300E	4dr sdn	FB4076GT	Heated Back Glass	Good	R1S1
1998	E series	ALL	FW818GY	Grey shaded windshield	Good - Minor cowl mark	R3S5

Nissan

79-85	280ZX	2dr cpe	FW390GT	Windshield	Some delamination	R1S3
-------	-------	---------	---------	------------	-------------------	------

2000	Altima	4dr sdn	FB20313GT	Heated back glass	Good	R1S7
2001	Frontier	4dr crew cab	FB21347YPY	Heated privacy back glass	Good	R2S13
1990	Pickup	ALL	FB5001GT	Heated back glass	Good	R2S13

Subaru

1999	Impreza	2dr Cpe	Part #	Left door glass	Good	U2
1990	Justy	2dr Htbk	FQ3485GT	Right rear quarter glass	Good	U1S14
1990	Justy	2dr Htbk	FQ3486GT	Left rear quarter glass	Good	U1S14
1995 - 1997	Legacy	4dr Wagon	FD5357GT	Right rear door glass	Good	U1S16
1995 - 1997	Legacy	4dr Wagon	FD5356GT	Left front door glass	Good	U1S15

Toyota

1985	Camry	4dr Htbk	FD2512GT	Left front door glass	Good	U1S19
1987	Camry	4dr sdn	FB3401GT	Heated back glass	Good	R1S14
1992	Camry	4dr sdn	FB4518GT	Heated back glass	Good	R1S14
1996	Corolla	4dr sdn	FB4694GT	Heated back glass	Good	R1S14
1997	Corolla	4dr sdn	FB4694GT	Heated back glass	Good	R1S14
1983	Pickup	ALL	FB5182GT	Back Glass	Good	R2S13
1981	Pickup	ALL	FB5182GT	Back Glass	Good	R1S2
1994	Pickup	ALL	FB2669ZT	Bronze Back Glass	Good	R2S13
1996	Pickup	ALL	FB4798GT	Back Glass	Good	R2S13
1994	4Runner	4dr utility	FB4083YP	Heated Privacy back glass	Good	R1S1
1997	Tacoma	ALL	FB5475	Back Glass	Good	R1S1
1987	Tercel	4dr Sdn	FB3420GT	Heated back glass	Good	R1S13
1992	Tercel	ALL	FB3420GT	Heated back glass	Good	R1S14
1994	Tercel	4dr Sdn	FD4409GT	Right rear door glass	Good	U1S19
1994	Tercel	4dr Sdn	FD4407GT	Right front door glass	Good	U1S18

Volkswagen

2002	Golf / GTI	ALL	FB20628GT	Heated back glass	Good	R1S6
------	------------	-----	-----------	-------------------	------	------